

U52-RW13  
PCI = 65


U52-AP2  
PCI = 100

U52-TL  
NOT MEASURED

U52-AP  
PCI = 73

**Beaver 6/21/2006**

|              |              |          |
|--------------|--------------|----------|
| Dark Green   | Excellent    | (86-100) |
| Bright Green | Very Good    | (71-85)  |
| Blue         | Good         | (56-70)  |
| Light Blue   | Fair         | (41-55)  |
| Yellow       | Poor         | (26-40)  |
| Pink         | Very Poor    | (11-25)  |
| Red          | Failed       | (0-10)   |
| Black        | NOT MEASURED |          |



BDG-R1  
PCI = 59

BDG-A1  
PCI = 50

BDG-A1  
PCI = 50

BDG-A1  
PCI = 50

BDG-A3  
PCI = 66


BDG-T1  
PCI = 72


BDG-A2  
PCI = 40

**Blanding 3/17/06**

|              |          |
|--------------|----------|
| Excellent    | (86-100) |
| Very Good    | (71-85)  |
| Good         | (56-70)  |
| Fair         | (41-55)  |
| Poor         | (26-40)  |
| Very Poor    | (11-25)  |
| Failed       | (0-10)   |
| NOT MEASURED |          |

59





BMCRWE2  
PCI = 92

BMCRWE1  
PCI = 74

BMC-R1  
PCI = 68

BMC-T1  
PCI = 76

BMC-A1  
PCI = 65

BMC-A2  
PCI = 58


BMC-A6  
PCI = 73

BMC-A5  
PCI = 45


BMC-A4  
PCI = 54

BMC-A3  
PCI = 66

BMC-T1  
PCI = 76




# BULLFROG




## Bullfrog 9/6/2006

|   |              |          |
|---|--------------|----------|
|  | Excellent    | (86-100) |
|  | Very Good    | (71-85)  |
|  | Good         | (56-70)  |
|  | Fair         | (41-55)  |
|  | Poor         | (26-40)  |
|  | Very Poor    | (11-25)  |
|  | Failed       | (0-10)   |
|  | NOT MEASURED |          |





# CEDAR



# DELTA



## Delta 9/2006


|  |              |          |
|--|--------------|----------|
|  | Excellent    | (86-100) |
|  | Very Good    | (71-85)  |
|  | Good         | (56-70)  |
|  | Fair         | (41-55)  |
|  | Poor         | (26-40)  |
|  | Very Poor    | (11-25)  |
|  | Failed       | (0-10)   |
|  | NOT MEASURED |          |

Duchesne 5/07


|              |          |              |
|--------------|----------|--------------|
| Excellent    | (86-100) | Preventative |
| Very Good    | (71-85)  | Preventative |
| Good         | (56-70)  | Rehab        |
| Fair         | (41-55)  | Rehab        |
| Poor         | (26-40)  | Reconstruct  |
| Very Poor    | (11-25)  | Reconstruct  |
| Failed       | (0-10)   | Reconstruct  |
| NOT MEASURED |          |              |

U69-R1  
PCI = 11

U69TA  
PCI = 2







# Dutch John




1L7-R1  
PCI = 54

1L7-A1  
PCI = 95

### Escalante 4/2007

|   |              |          |
|---|--------------|----------|
|  | Excellent    | (86-100) |
|  | Very Good    | (71-85)  |
|  | Good         | (56-70)  |
|  | Fair         | (41-55)  |
|  | Poor         | (26-40)  |
|  | Very Poor    | (11-25)  |
|  | Failed       | (0-10)   |
|  | NOT MEASURED |          |



Fillmore 10/2007

|              |          |              |
|--------------|----------|--------------|
| Excellent    | (86-100) | Preventative |
| Very Good    | (71-85)  | Preventative |
| Good         | (56-70)  | Rehab        |
| Fair         | (41-55)  | Rehab        |
| Poor         | (26-40)  | Reconstruct  |
| Very Poor    | (11-25)  | Reconstruct  |
| Failed       | (0-10)   | Reconstruct  |
| NOT MEASURED |          |              |

FOM-AT-old  
PCI = 47

FOM-A2  
PCI = 100

FOM-T1  
PCI = 100


FOM-R1  
PCI = 100

FOM-TRN  
PCI = 100


22


4





# Halls Crossing






HVE-R1  
PCI = 34

HVE-AT1  
PCI = 42

HVE-TL  
PCI = 100


Hanksville 5/2007

|              |              |          |
|--------------|--------------|----------|
| Dark Green   | Excellent    | (86-100) |
| Bright Green | Very Good    | (71-85)  |
| Blue         | Good         | (56-70)  |
| Light Blue   | Fair         | (41-55)  |
| Yellow       | Poor         | (26-40)  |
| Pink         | Very Poor    | (11-25)  |
| Red          | Failed       | (0-10)   |
| Black        | NOT MEASURED |          |



Heber 6/2007

|              |          |              |
|--------------|----------|--------------|
| Excellent    | (86-100) | Preventative |
| Very Good    | (71-85)  | Preventative |
| Good         | (56-70)  | Rehab        |
| Fair         | (41-55)  | Rehab        |
| Poor         | (26-40)  | Reconstruct  |
| Very Poor    | (11-25)  | Reconstruct  |
| Failed       | (0-10)   | Reconstruct  |
| NOT MEASURED |          |              |



69V-A1  
PCI = 79


69V-R1  
PCI = 70

69V-A2  
PCI = 78

Huntington 9/2007

|  |              |                       |
|--|--------------|-----------------------|
|  | Excellent    | (86-100) Preventative |
|  | Very Good    | (71-85) Preventative  |
|  | Good         | (56-70) Rehab         |
|  | Fair         | (41-55) Rehab         |
|  | Poor         | (26-40) Reconstruct   |
|  | Very Poor    | (11-25) Reconstruct   |
|  | Failed       | (0-10) Reconstruct    |
|  | NOT MEASURED |                       |

# Hurricane




# JUNCTION AIRPORT


U13-R1  
PCI = 59

U13-TA  
PCI = 53

## Junction 5/2006

|  |              |          |
|--|--------------|----------|
|  | Excellent    | (86-100) |
|  | Very Good    | (71-85)  |
|  | Good         | (56-70)  |
|  | Fair         | (41-55)  |
|  | Poor         | (26-40)  |
|  | Very Poor    | (11-25)  |
|  | Failed       | (0-10)   |
|  | NOT MEASURED |          |





KNB-R1  
PCI = 98

KNB-T1-A1  
PCI = 64

KNB-A2  
PCI = 41

KNB-A1  
PCI = 52

KNB-T1  
PCI = 45

KNB-T1-A3  
PCI = 69

**Kanab 10/2007**

|              |                       |
|--------------|-----------------------|
| Excellent    | (86-100) Preventative |
| Very Good    | (71-85) Preventative  |
| Good         | (56-70) Rehab         |
| Fair         | (41-55) Rehab         |
| Poor         | (26-40) Reconstruct   |
| Very Poor    | (11-25) Reconstruct   |
| Failed       | (0-10) Reconstruct    |
| NOT MEASURED |                       |





# LOA, UTAH


5890' x 75'

PCI = 61  
38U-R1


PCI = 57  
38U-TA1


Loa 6/2006

|   |              |          |
|---|--------------|----------|
|  | Excellent    | (86-100) |
|  | Very Good    | (71-85)  |
|  | Good         | (56-70)  |
|  | Fair         | (41-55)  |
|  | Poor         | (26-40)  |
|  | Very Poor    | (11-25)  |
|  | Failed       | (0-10)   |
|  | NOT MEASURED |          |



# Logan 5/2006


|  |              |          |
|--|--------------|----------|
|  | Excellent    | (86-100) |
|  | Very Good    | (71-85)  |
|  | Good         | (56-70)  |
|  | Fair         | (41-55)  |
|  | Poor         | (26-40)  |
|  | Very Poor    | (11-25)  |
|  | Failed       | (0-10)   |
|  | NOT MEASURED |          |





Manilla 6/2007

|   |              |                       |
|---|--------------|-----------------------|
| <span style="display: inline-block; width: 15px; height: 15px; background-color: #006400; border: 1px solid black;"></span> | Excellent    | (86-100) Preventative |
| <span style="display: inline-block; width: 15px; height: 15px; background-color: #00FF00; border: 1px solid black;"></span> | Very Good    | (71-85) Preventative  |
| <span style="display: inline-block; width: 15px; height: 15px; background-color: #0000FF; border: 1px solid black;"></span> | Good         | (56-70) Rehab         |
| <span style="display: inline-block; width: 15px; height: 15px; background-color: #ADD8E6; border: 1px solid black;"></span> | Fair         | (41-55) Rehab         |
| <span style="display: inline-block; width: 15px; height: 15px; background-color: #FFFF00; border: 1px solid black;"></span> | Poor         | (26-40) Reconstruct   |
| <span style="display: inline-block; width: 15px; height: 15px; background-color: #FF00FF; border: 1px solid black;"></span> | Very Poor    | (11-25) Reconstruct   |
| <span style="display: inline-block; width: 15px; height: 15px; background-color: #FF0000; border: 1px solid black;"></span> | Failed       | (0-10) Reconstruct    |
| <span style="display: inline-block; width: 15px; height: 15px; background-color: #000000; border: 1px solid black;"></span> | NOT MEASURED |                       |




Milford 6/2007

|              |                       |
|--------------|-----------------------|
| Excellent    | (86-100) Preventative |
| Very Good    | (71-85) Preventative  |
| Good         | (56-70) Rehab         |
| Fair         | (41-55) Rehab         |
| Poor         | (26-40) Reconstruct   |
| Very Poor    | (11-25) Reconstruct   |
| Failed       | (0-10) Reconstruct    |
| NOT MEASURED |                       |




# MOAB



MOAB 2001

Moab 2/8/2006



96






U43-R1  
PCI = 76

U43-T1  
PCI = 96


U43-A1  
PCI = 84

34

### Monticello 2006

|   |              |          |
|---|--------------|----------|
|  | Excellent    | (86-100) |
|  | Very Good    | (71-85)  |
|  | Good         | (56-70)  |
|  | Fair         | (41-55)  |
|  | Poor         | (26-40)  |
|  | Very Poor    | (11-25)  |
|  | Failed       | (0-10)   |
|  | NOT MEASURED |          |

# MORGAN





42U-R1  
PCI = 77

42U-A1  
PCI = 61

Morgan 8/2006

|              |              |          |
|--------------|--------------|----------|
| Dark Green   | Excellent    | (86-100) |
| Bright Green | Very Good    | (71-85)  |
| Blue         | Good         | (56-70)  |
| Light Blue   | Fair         | (41-55)  |
| Yellow       | Poor         | (26-40)  |
| Pink         | Very Poor    | (11-25)  |
| Red          | Failed       | (0-10)   |
| Black        | NOT MEASURED |          |





U14-RWNEW  
PCI = 98

U14-TWNEW  
PCI = 100


U14-APNEW  
PCI = 65


Nephi 6/2007

|              |          |              |
|--------------|----------|--------------|
| Excellent    | (86-100) | Preventative |
| Very Good    | (71-85)  | Preventative |
| Good         | (56-70)  | Rehab        |
| Fair         | (41-55)  | Rehab        |
| Poor         | (26-40)  | Reconstruct  |
| Very Poor    | (11-25)  | Reconstruct  |
| Failed       | (0-10)   | Reconstruct  |
| NOT MEASURED |          |              |

Ogden 10/2007

|              |                       |
|--------------|-----------------------|
| Excellent    | (86-100) Preventative |
| Very Good    | (71-85) Preventative  |
| Good         | (56-70) Rehab         |
| Fair         | (41-55) Rehab         |
| Poor         | (26-40) Reconstruct   |
| Very Poor    | (11-25) Reconstruct   |
| Failed       | (0-10) Reconstruct    |
| NOT MEASURED |                       |





U55-A2  
PCI = 72


U55-TA1  
PCI = 49

U55-A3  
PCI = 74

U55-R1  
PCI = 72

Panguitch 6/2007

|              |          |              |
|--------------|----------|--------------|
| Excellent    | (86-100) | Preventative |
| Very Good    | (71-85)  | Preventative |
| Good         | (56-70)  | Rehab        |
| Fair         | (41-55)  | Rehab        |
| Poor         | (26-40)  | Reconstruct  |
| Very Poor    | (11-25)  | Reconstruct  |
| Failed       | (0-10)   | Reconstruct  |
| NOT MEASURED |          |              |



1L9 A1  
PCI = 71


1L9-T1  
PCI = 74

1L9-R1  
PCI = 68


1L9-A2  
PCI = 72

Parowan 6-2006

|              |              |          |
|--------------|--------------|----------|
| Dark Green   | Excellent    | (86-100) |
| Bright Green | Very Good    | (71-85)  |
| Blue         | Good         | (56-70)  |
| Light Blue   | Fair         | (41-55)  |
| Yellow       | Poor         | (26-40)  |
| Pink         | Very Poor    | (11-25)  |
| Red          | Failed       | (0-10)   |
| Black        | NOT MEASURED |          |




# PROVO



Provo 9/2006

- Excellent (86-100)
- Very Good (71-85)
- Good (56-70)
- Fair (41-55)
- Poor (26-40)
- Very Poor (11-25)
- Failed (0-10)
- NOT MEASURED



RIF-A2-3 (concrete)  
PCI = 92

RIF-A1  
PCI = 72

RIF-TW  
PCI=58


RIF-A2-2  
PCI = 74

RIF-A2-1  
PCI = 58

RIF-R1  
PCI = 63

**Richfield 6/2008**

|   |              |                       |
|---|--------------|-----------------------|
|  | Excellent    | (86-100) Preventative |
|  | Very Good    | (71-85) Preventative  |
|  | Good         | (56-70) Rehab         |
|  | Fair         | (41-55) Rehab         |
|  | Poor         | (26-40) Reconstruct   |
|  | Very Poor    | (11-25) Reconstruct   |
|  | Failed       | (0-10) Reconstruct    |
|  | NOT MEASURED |                       |



74V-R1  
PCI = 78

74V-A2  
PCI = 57

74V-TA  
PCI = 66

Roosevelt-update-shift.shp

|              |              |          |              |
|--------------|--------------|----------|--------------|
| Dark Green   | Excellent    | (86-100) | Preventative |
| Bright Green | Very Good    | (71-85)  | Preventative |
| Blue         | Good         | (56-70)  | Rehab        |
| Light Blue   | Fair         | (41-55)  | Rehab        |
| Yellow       | Poor         | (26-40)  | Reconstruct  |
| Pink         | Very Poor    | (11-25)  | Reconstruct  |
| Red          | Failed       | (0-10)   | Reconstruct  |
| Black        | NOT MEASURED |          |              |


# SALINA - GUNNISON

44U-AT1  
PCI = 53


44U-R1  
PCI = 59

Salina 5/2007

|              |                       |
|--------------|-----------------------|
| Excellent    | (86-100) Preventative |
| Very Good    | (71-85) Preventative  |
| Good         | (56-70) Rehab         |
| Fair         | (41-55) Rehab         |
| Poor         | (26-40) Reconstruct   |
| Very Poor    | (11-25) Reconstruct   |
| Failed       | (0-10) Reconstruct    |
| NOT MEASURED |                       |




# BOUNTIFUL



## Skypark 2005

|   |              |          |
|---|--------------|----------|
|  | Excellent    | (86-100) |
|  | Very Good    | (71-85)  |
|  | Good         | (56-70)  |
|  | Fair         | (41-55)  |
|  | Poor         | (26-40)  |
|  | Very Poor    | (11-25)  |
|  | Failed       | (0-10)   |
|  | NOT MEASURED |          |

# Spanish Fork







St george 2006

|              |              |          |
|--------------|--------------|----------|
| Dark Green   | Excellent    | (86-100) |
| Bright Green | Very Good    | (71-85)  |
| Blue         | Good         | (56-70)  |
| Light Blue   | Fair         | (41-55)  |
| Yellow       | Poor         | (26-40)  |
| Pink         | Very Poor    | (11-25)  |
| Red          | Failed       | (0-10)   |
| Black        | NOT MEASURED |          |

# VERNAL





Wendover 3/2008

|              |          |              |
|--------------|----------|--------------|
| Excellent    | (86-100) | Preventative |
| Very Good    | (71-85)  | Preventative |
| Good         | (56-70)  | Rehab        |
| Fair         | (41-55)  | Rehab        |
| Poor         | (26-40)  | Reconstruct  |
| Very Poor    | (11-25)  | Reconstruct  |
| Failed       | (0-10)   | Reconstruct  |
| NOT MEASURED |          |              |